Flex mount installation instructions

Parts List

60085 x1	60525 x1	101817 x2	Bottom Clamp '1' x1	Adapter x1
60080 x1	60516 x4	101819 x1	Main Body '2' x1	Top Clamp '3' x1
		17SPF-RAIL-8, 12 or 15 x1	Top Clamp '4' x1	Lever Assembly x1

Tools Required

	Power drill
	Hole Saw ø16mm (5/8"), ø24mm (15/16")
	ø7.0mm
	13mm Socket Wrench

Tools Included

	M5 Pin torx Wrench (63516)

1



2



3 Cable Installation

3 Suggested Routing (3 Cables)



4



Southmoor Lane, Havant, Hampshire, P09 1JJ UK | Tel: +44 (0) 2392 471841 | Fax: +44 (0) 2392 485720 | **www.lewmar.com**